

# DIGITUS Fiber Optic Multimode Patchcord, OM4, LC / LC

DK-2533-02-4 EAN 4016032308805





## FO patch cord, duplex, LC to LC MM OM4 50/125 $\mu,\,2$ m

FO patch cord, duplex, LC to LC,MM OM4 50/125  $\mu,\,2$  m

# Future-oriented standards and high-end quality for your network.


- Duplex cable
- LSÖH
- Connector with ceramic ferrule
- Cable diameter 2 mm
- Single packed with test-report
- Color: RAL 4003

#### **Attributes**

- Assortment: Fiber Optic Patch Cables
- Cable diameter: 2 mm
- · Color cable: erika violet
- · Connector 1: LC
- Connector 2: LC
- Fiber class: OM4Fiber diameter: 50/125µ
- Mode: Multimode
- Length: 2 m

ogistics							
	Number (pcs)	Weight (kg)	Depth (cm)	Width (cm)	Height (cm)	cm³	
Packaging Unit Carton	120	9.00	41.00	41.00	28.00	47,068.00	
Packaging Unit Inside	15	1.13	19.00	19.00	12.00	4,332.00	
Packaging Unit Single	1	0.08	17.00	17.00	1.00	289.00	
Net single without Packaging	1	0.05	15.00	15.00	1.00	0.00	

### More images:



Part No.	DK-2533-02-4						
Lenght	2 m						
Cable Type	Duplex N	IM 50/125	OM4 LSZH				
	END A		END B				
Connector Type	LC		LC				
Insertion Loss (dB)	0.06	0.09	0.17	0.11			
Return Loss (dB)	37.7	30.1	39.5	39.7			
Q.C.	PASS						







#### Safety notes

- Avoid direct contact with light sources: Fiber optic cables, especially those with active light sources such as lasers (e.g. in optical communication systems), can emit dangerous radiation that can damage
- eyes. Take care never to look directly into the light of an optical fiber, even if the light source is invisible to the naked eye.
- When working with fiber optic cables, especially during tests or when working with lasers, protective goggles should always be worn to protect
  against harmful radiation.
- When plugging and unplugging the cable, only grasp the plug and do not pull directly on the cable.
- Do not kink or crush: Fiber optic cables are sensitive to mechanical stress.
- · To protect cables from physical damage, they should be laid in special ducts or with protective materials
- Keep cable connectors clean: Fiber optic cables are sensitive to dust and dirt. Even small particles on the connectors can severely impair the signal quality.
- Cables should not be used in environments with extremely high or very low temperatures. Observe the product information on the maximum
  operating temperature of the cable
- · Check cables regularly for visible damage such as cracks, kinks or signs of wear. Defective cables should be replaced immediately.

#### EU responsible person

EU based economic operator ensuring the product complies with the required regulations.

ASSMANN Electronic GmbH Auf dem Schüffel 3 Lüdenscheid, Germany https://www.assmann.com info@assmann.com